



- QE01-QE02  
HC1010030  
STK-6325A
- QE03-Q405  
HC1000890  
NJM45580-D
- QY01-QY05, QK02, QK05  
HT111752B  
25A1175
- QK01, QK03, QK04, Q709, Q710  
HT327852B1  
25C2785
- Q501  
HC10110030  
LC7815H
- Q502  
HC406603C0  
LC4066B-H
- Q401-Q404  
HF203691G0  
25K369
- Q701, Q702  
HT413028B1  
25D1302
- Q703, Q704  
HC10097060  
µPC1270H
- Q705, Q706  
HT325802A0  
25C2578
- Q707, Q708  
HT11052A0  
25A1103
- Q801  
HT20507200  
25B507
- DK01, D501, D401, D402, D701-Q704  
HD20001001  
1S1555
- DK02, D808  
HD30045011  
HZ26C
- DK03, D801, D802  
HD30038011  
1S2472
- DK04  
HD20022031  
DSF60C
- D705, D706  
HW00009080  
STV3H
- D805  
HD20008290  
S4V8
- D806, D807  
HD30026021  
D5135D
- D502  
HD30045011  
HZ06L



**NOTE ON SAFETY:**  
 Symbol ⚠ Fire or electrical shock hazard. Only original parts should be used to replace any part marked with symbol ⚠. Any other component substitution (other than original type); may increase risk of fire or electrical shock hazard.

Components and wiring are subject to change for modification without notice.