


S	987 989														
C	1055	1046	1054	1045	1052	1047	1043	1051	1044	1053	1041				
C	1125	1124	1116	1115	1122	1117	1042	1121	1114	1123	1111				
R	1228	1237	1232	1236	1222	1238	1219+1221	1229	1230	1226	1227	1241+1245	1215+1218	1207+1212	1239
R	1348	1357	1358	1352	1356	1342	1339+1341	1349	1347	1346	1350	1361+1365	1335+1338	1329+1332	1359



- TS 962  
e = 0 V  
b = 0.4 V  
c = 10 V
- TS 961  
e = 2.8 V  
b = 2.2 V  
c = 0.6 V
- TS 951  
e = 2.8 V  
c = 2.2 V  
c = 0.6 V
- TS 952  
e = 0 V  
b = 0.4 V  
c = 10 V
- TS 963  
e = 2.5 V  
b = 2 V  
c = 0.6 V
- TS 956  
e = 7.5 V  
b = 6.9 V  
c = 2.8 V
- TS 957  
e = 0.04 V  
b = 0.6 V  
c = 21.6 V
- TS 967  
e = 0.04 V  
b = 0.6 V  
c = 21.6 V
- TS 966  
e = 7.5 V  
b = 6.9 V  
c = 2.8 V
- TS 965  
e = 0 V  
b = 0.4 V  
c = 7 V

- TS 972  
k=22V
- TS 959b  
e = 23.3 V  
b = 23.9 V  
c = 45 V
- TS 959a  
e = 22.2 V  
b = 21.6 V  
c = 0.6 V
- TS 969a  
e = 22.2 V  
b = 21.6 V  
c = 0.6 V
- TS 969b  
e = 23.3 V  
b = 23.9 V  
c = 45 V
- TS 973  
k=22V

- TS 958  
e = 21.6 V  
b = 22.2 V  
c = 23.9 V
- TS 956  
e = 7.5 V  
b = 6.9 V  
c = 2.8 V
- TS 957  
e = 0.04 V  
b = 0.6 V  
c = 21.6 V
- TS 967  
e = 0.04 V  
b = 0.6 V  
c = 21.6 V
- TS 966  
e = 7.5 V  
b = 6.9 V  
c = 2.8 V
- TS 968  
e = 21.6 V  
b = 22.2 V  
c = 23.9 V

TS951 + 956, TS958  
TS961 + 966, TS968

TS957, 959a, b  
TS967, 969a, b

